

Third walkthrough video

Time	Hazard	Photo	Category
00:28	Incorrect lab coat	 A male lab technician with a beard and safety glasses is working at a lab bench. He is wearing a white lab coat over dark clothing. He is using a pipette to transfer liquid into small vials. The lab bench is equipped with various glassware, including beakers and flasks, and some equipment. The background shows a window with a grid pattern.	

00:34	Trip hazards – chairs left out		
1:03	Aseptic technique not applied		

1:18	Open plate with bacteria on untidy work area			
1:33	Overfilled bin with microbiological waste			

2:10	Unlabelled reagents				
2:29	Broken glass and spilt liquid				

3:03	Waste – potentially contaminated				
3:22	Equipment stacked on top of other equipment				

4:45	Open lab coat				
5:38	Phone out in microbiology lab				

6:06	Kink in Bunsen burner tubing			
------	------------------------------	--	--	--

St John Rigby College is delivering this programme on behalf of the Education and Training Foundation. This programme is funded by the Department for Education.